

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

[The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the potential limitation. The columns that identify the rating class and limiting features show no more than five limitations for any given soil. The soil may have additional limitations. This report shows only the major soils in each map unit]

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
100: Balcom	75	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
101: Balcom	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Nacimiento	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
102: Balcom	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Nacimiento	30	Severe Slope/erodibility Slope/erodibility	0.75 0.75	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
103: Balcom	45	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50
Nacimiento	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
109: Capay	80	Slight		Slight		Moderately suited Low strength	0.50
110: Capay	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
112: Calleguas	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
112: Balcom	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
114: Calleguas	55	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Nacimiento	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
120: Hillbrick	65	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	15	Severe Slope/erodibility Slope/erodibility	0.75 0.50	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
121: Hillbrick	65	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	15	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
123: Lithic Torriorthents	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Semper	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	20	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
129: Kilmer	40	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
129: Hillbrick	35	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
130: Kilmer	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Hillbrick	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
131: Kilmer	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Hillbrick	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
134: Kilmer	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Nacimiento	25	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Aido	15	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
140: Choice	80	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
149: San Emigdio	80	Slight		Slight		Well suited	
150: San Emigdio	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
154: San Emigdio	85	Slight		Slight		Moderately suited Low strength	0.50

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
155: San Emigdio	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
159: Sorrento	85	Slight		Slight		Moderately suited Low strength	0.50
160: Sorrento	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
169: Polonio	75	Slight		Slight		Moderately suited Low strength	0.50
170: Polonio	65	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
173: Polonio	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
174: Polonio	50	Slight		Slight		Well suited	
Thomhill	30	Slight		Slight		Moderately suited Low strength	0.50
175: Polonio	50	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Thomhill	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
179: Padres	70	Slight		Slight		Well suited	
180: Padres	65	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
182: Oceano	50	Slight		Moderate Slope/erodibility	0.50	Moderately suited Sandiness Slope	0.50 0.50
190: Reward	70	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
191: Reward	70	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
200: Aramburu	70	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
201: Aramburu	65	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
202: Aramburu	65	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
204: Aramburu	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Temblor	35	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
205: Aramburu	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Temblor	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
218: Seaback	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
218:							
Calleguas	25	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	20	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
219:							
Xerorthents	50	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Badlands	35	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
220:							
Beam	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Hillbrick	15	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
221:							
Beam	35	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Hillbrick	15	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
222:							
Beam	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Hillbrick	15	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
227:							
Beam	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
228:							
Beam	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
229:							
Seaback	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Timoteo	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
230:							
Padres	50	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Wasioja	35	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
240:							
Panoza	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Beam	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
241:							
Panoza	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Beam	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
242:							
Panoza	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Beam	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
248:							
Pyxo	55	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Landslides Low strength	1.00 1.00 0.50
Cochora	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Landslides	1.00 1.00
249:							
Xeric Torriorthents	50	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Badlands	25	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
250:							
Pyxo	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Landslides	1.00 1.00
Cochora	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Landslides	1.00 1.00
Badlands	15	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
251:							
Nacimiento	75	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
252:							
Nacimiento	75	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
261: Aido	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
262: Aido	80	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
263: Aido	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
270: Ayar	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope Stickiness; high plasticity index	0.50 0.50 0.50
271: Ayar	80	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
274: Ayar	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Stickiness; high plasticity index	1.00 0.50
Hillbrick	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Aido	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
275: Ayar	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Stickiness; high plasticity index	1.00 0.50
Hillbrick	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
275:							
Aido	20	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
280:							
Seaback	35	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
Panoza	30	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
Jenks	15	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
281:							
Seaback	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Jenks	15	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
282:							
Seaback	35	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Jenks	15	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
290:							
San Timoteo	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Bellyspring	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
291:							
San Timoteo	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	25	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Bellyspring	20	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
292:							
San Timoteo	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Bellyspring	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
301:							
Arbuckle	70	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
302:							
Arbuckle	70	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
303:							
Arbuckle	70	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
304:							
Arbuckle	70	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
306:							
Arbuckle	70	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
307:							
Arbuckle	70	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
310: Pinspring	40	Slight		Slight		Moderately suited Low strength	0.50
Yeguas	40	Slight		Slight		Moderately suited Low strength	0.50
311: Pinspring	40	Slight		Moderate Slope/erodibility	0.50	Well suited	
Yeguas	40	Slight		Moderate Slope/erodibility	0.50	Well suited	
321: Thomhill	80	Slight		Moderate Slope/erodibility	0.50	Well suited	
330: Jenks	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
339: Arnold	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
340: Arnold	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
350: Cieneba	75	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
360:							
Chicote, silty clay loam	40	Slight		Slight		Poorly suited	
						Ponding	1.00
						Stickiness; high plasticity index	0.50
						Low strength	0.50
Chicote, silt loam	40	Slight		Slight		Poorly suited	
						Ponding	1.00
						Low strength	0.50
361:							
Chicote, silty clay loam	40	Slight		Moderate		Poorly suited	
				Slope/erodibility	0.50	Ponding	1.00
						Stickiness; high plasticity index	0.50
Chicote, silt loam	40	Slight		Moderate		Poorly suited	
				Slope/erodibility	0.50	Ponding	1.00
362:							
Chicote, silty clay loam	40	Slight		Moderate		Poorly suited	
				Slope/erodibility	0.50	Ponding	1.00
						Stickiness; high plasticity index	0.50
						Slope	0.50
Chicote, silt loam	40	Slight		Moderate		Poorly suited	
				Slope/erodibility	0.50	Ponding	1.00
						Slope	0.50
371:							
Semper	50	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
372:							
Semper	65	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
375:							
Semper	40	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
Badlands	25	Not rated		Not rated		Not rated	

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
380:							
Muranch	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Xerorthents	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	20	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
388:							
Rock outcrop	50	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
Gaviota	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
391:							
Rock outcrop	35	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
Lithic Torriorthents	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
401:							
Godde	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Xerorthents	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	15	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
408:							
Gaviota	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
409:							
Gaviota	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Saltos	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	15	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
410:							
Gaviota	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	30	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
411:							
Saltos	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Tajea	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
412:							
Tajea	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Saltos	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
420:							
Bellyspring	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Saltos	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
420:							
Rock outcrop	20	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
		Slope/erodibility	0.95	Slope/erodibility	0.95		
430:							
Saucito	40	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
Akad	25	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
						Low strength	0.50
Rock outcrop	20	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
		Slope/erodibility	0.95	Slope/erodibility	0.95		
440:							
Bellyspring	35	Slight		Severe		Moderately suited	
				Slope/erodibility	0.95	Slope	0.50
Panoza	25	Slight		Severe		Moderately suited	
				Slope/erodibility	0.95	Slope	0.50
441:							
Bellyspring	35	Moderate		Severe		Poorly suited	
		Slope/erodibility	0.50	Slope/erodibility	0.95	Slope	1.00
Panoza	30	Moderate		Severe		Poorly suited	
		Slope/erodibility	0.50	Slope/erodibility	0.95	Slope	1.00
442:							
Bellyspring	35	Severe		Severe		Poorly suited	
		Slope/erodibility	0.75	Slope/erodibility	0.95	Slope	1.00
Panoza	30	Severe		Severe		Poorly suited	
		Slope/erodibility	0.75	Slope/erodibility	0.95	Slope	1.00
443:							
Bellyspring	35	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
Beam	25	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
443: Panoza	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
445: Bellyspring	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Xerorthents	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Panoza	15	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
450: Botella	75	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
460: Camatta	75	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
470: Botella	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
474: Elder	80	Slight		Slight		Well suited	
475: Elder	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
480: Metz	70	Slight		Moderate Slope/erodibility	0.50	Well suited	
490: Wasioja	75	Slight		Slight		Moderately suited Low strength	0.50

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
491: Wasioja	85	Slight		Moderate Slope/erodibility	0.50	Well suited	
495: Wasioja	60	Slight		Moderate Slope/erodibility	0.50	Well suited	
Polonio	20	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength	0.50
497: Wasioja	35	Slight		Moderate Slope/erodibility	0.50	Well suited	
Pinspring	30	Slight		Moderate Slope/erodibility	0.50	Well suited	
Yeguas	15	Slight		Moderate Slope/erodibility	0.50	Well suited	
512: Shimmon	80	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
520: Santa Lucia	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
521: Santa Lucia	80	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
522: Santa Lucia	55	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
531: Saltos	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Millsholm	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
561: Chanac	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
562: Chanac	90	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
900: Pits	100	Slight		Slight		Moderately suited Ponding Flooding	0.50 0.50
905: Xerofluvents	50	Slight		Slight		Poorly suited Flooding	1.00
Riverwash	30	Slight		Slight		Poorly suited Flooding Wetness Sandiness	1.00 0.50 0.50
906: Xerofluvents	85	Slight		Slight		Moderately suited Ponding Flooding	0.50 0.50
908: Xerorthents	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
910: Playas	80	Slight		Slight		Poorly suited Ponding Wetness Low strength Stickiness; high plasticity index	1.00 1.00 0.50 0.50
911: Playas	85	Slight		Slight		Poorly suited Ponding Wetness Stickiness; high plasticity index	1.00 1.00 0.50

# Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Carrizo Plain Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
912: Water	100	Not rated		Not rated		Not rated	