

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

[The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the potential limitation. The columns that identify the rating class and limiting features show no more than five limitations for any given soil. The soil may have additional limitations. This report shows only the major soils in each map unit]

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
101: Aquolls	85	Slight		Slight		Poorly suited Flooding Wetness	1.00 1.00
102: Arnold	85	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
103: Arnold	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
104: Baywood	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
105: Baywood	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
106: Baywood	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
107: Beaches	90	Slight		Slight		Poorly suited Flooding Sandiness	1.00 0.50
108: Briones	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
109: Briones	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Pismo	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
110: Briones	50	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Tierra	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
111: Camarillo	85	Slight		Slight		Well suited	
112: Camarillo	85	Slight		Slight		Moderately suited Low strength	0.50
113: Capistrano	85	Slight		Slight		Well suited	
114: Capistrano	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
115: Chamise	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
116: Chamise	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
117: Chamise	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
118: Cieneba	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Kinkel variant	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Sandiness Low strength	1.00 0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
119:							
Cieneba	50	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Millsap	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
120:							
Concepcion	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength	0.50
121:							
Concepcion	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
122:							
Concepcion	85	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50
123:							
Concepcion	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
124:							
Corralitos	85	Slight		Slight		Moderately suited Sandiness	0.50
125:							
Corralitos	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Sandiness	0.50 0.50
126:							
Corralitos variant	85	Slight		Slight		Moderately suited Flooding	0.50
127:							
Cropley	85	Slight		Slight		Moderately suited Low strength	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
128: Cropley	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
129: Diablo	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope Stickiness; high plasticity index	0.50 0.50 0.50
130: Cibo	45	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Stickiness; high plasticity index Low strength	0.50 0.50 0.50
Diablo	45	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Low strength Stickiness; high plasticity index	0.50 0.50 0.50
131: Cibo	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Stickiness; high plasticity index Low strength	1.00 0.50 0.50
Diablo	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
132: Cibo	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Stickiness; high plasticity index Low strength	1.00 0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
132:							
Diablo	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
133:							
Diablo	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
Lodo	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
134:							
Dune land	90	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Sandiness	1.00 0.50
135:							
Elder	85	Slight		Moderate Slope/erodibility	0.50	Well suited	
136:							
Elder	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
137:							
Elder	85	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
138:							
Elder	85	Slight		Slight		Moderately suited Flooding	0.50
139:							
Elder	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Flooding Slope	0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
140: Garey	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
141: Gaviota	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
142: Gaviota	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
143: Gazos	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Lodo	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
144: Gazos	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Lodo	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
145: Gazos	45	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Lodo	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
146: Henneke	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
146: Rock outcrop	35	Very severe Slope/erodibility Slope/erodibility	0.95 0.75	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
147: Lodo	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Low strength	0.50 0.50
148: Lodo	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
149: Lodo	85	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
150: Lodo	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
151: Lodo	55	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	40	Moderate Slope/erodibility Slope/erodibility	0.50 0.50	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
152: Lodo	55	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	35	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
153:							
Lompico	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
McMullin	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
154:							
Lompico	45	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
McMullin	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
155:							
Lopez	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
156:							
Lopez	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
157:							
Lopez	60	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	35	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
158:							
Los Osos	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
159:							
Los Osos	85	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
160: Los Osos	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
161: Los Osos	85	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
162: Los Osos	35	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
Diablo	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope Stickiness; high plasticity index	0.50 0.50 0.50
163: Los Osos	35	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50
Diablo	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Low strength Stickiness; high plasticity index	0.50 0.50 0.50
164: Los Osos	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Diablo	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
165:							
Los Osos	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Diablo	35	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
166:							
Los Osos	50	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Lodo	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
167:							
Los Osos	50	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Lodo	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
168:							
Los Osos variant	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
169:							
Marimel	85	Slight		Slight		Moderately suited Flooding	0.50
170:							
Marimel	85	Slight		Slight		Moderately suited Low strength	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
171: Millsap	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
172: Millsap	60	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	20	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
173: Mocho	85	Slight		Slight		Well suited	
174: Mocho	85	Slight		Slight		Moderately suited Low strength	0.50
175: Mocho	85	Slight		Slight		Moderately suited Sandiness Low strength	0.50 0.50
176: Mocho variant	85	Slight		Slight		Well suited	
177: Nacimiento	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
178: Nacimiento	85	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
179: Nacimiento	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
180:							
Nacimiento	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Calodo	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
181:							
Nacimiento	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Calodo	35	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
182:							
Calodo	45	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Nacimiento	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
183:							
Obispo	50	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	30	Very severe Slope/erodibility Slope/erodibility	0.95 0.75	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
184:							
Oceano	85	Slight		Slight		Moderately suited Sandiness	0.50
185:							
Oceano	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Sandiness	1.00 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
186: Perkins	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
187: Perkins	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
188: Perkins	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
189: Pismo	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
190: Pismo	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	35	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
191: Pismo	40	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Tierra	30	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
192: Fluents	45	Slight		Slight		Moderately suited Flooding	0.50
Psamments	45	Slight		Slight		Moderately suited Flooding Sandiness	0.50 0.50
193: Fluents	45	Slight		Slight		Moderately suited Wetness Flooding	0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
193: Psammets	45	Slight		Slight		Moderately suited	
						Wetness	0.50
						Flooding	0.50
194: Riverwash	90	Slight		Slight		Poorly suited	
						Flooding	1.00
						Wetness	0.50
						Sandiness	0.50
195: Rock outcrop	55	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
		Slope/erodibility	0.95	Slope/erodibility	0.95		
Lithic Haploxerolls	25	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
		Slope/erodibility	0.95	Slope/erodibility	0.95		
196: Salinas	85	Slight		Slight		Moderately suited	
						Low strength	0.50
197: Salinas	85	Slight		Slight		Moderately suited	
						Low strength	0.50
198: Salinas	85	Slight		Moderate		Moderately suited	
				Slope/erodibility	0.50	Low strength	0.50
						Slope	0.50
199: San Simeon	85	Slight		Moderate		Moderately suited	
				Slope/erodibility	0.50	Slope	0.50
200: San Simeon	85	Slight		Severe		Moderately suited	
				Slope/erodibility	0.95	Slope	0.50
201: San Simeon	85	Moderate		Severe		Poorly suited	
		Slope/erodibility	0.50	Slope/erodibility	0.95	Slope	1.00

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
202: San Simeon	85	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
203: Santa Lucia	85	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
204: Santa Lucia	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
205: Santa Lucia	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
206: Santa Lucia	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
207: Santa Lucia	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
208: Still	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
209: Still	85	Slight		Slight		Well suited	
210: Still	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
211: Still	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
212: Suey	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
213: Suey	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50
214: Suey	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
215: Suey	85	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
216: Tierra	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
217: Tierra	85	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50
218: Tierra	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
219: Tujunga	85	Slight		Slight		Moderately suited Flooding Sandiness	0.50 0.50
220: Tujunga	85	Slight		Moderate Slope/erodibility	0.50	Poorly suited Flooding Sandiness Slope	1.00 0.50 0.50
221: Xererts	30	Slight		Moderate Slope/erodibility Slope/erodibility	0.50 0.50	Moderately suited Slope	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
221:							
Xerolls	30	Slight		Moderate		Moderately suited	
				Slope/erodibility	0.50	Slope	0.50
				Slope/erodibility	0.50		
Urban land	20	Slight		Moderate		Moderately suited	
				Slope/erodibility	0.50	Slope	0.50
				Slope/erodibility	0.50		
222:							
Xerorthents	85	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
		Slope/erodibility	0.95	Slope/erodibility	0.95		
223:							
Xerorthents	85	Severe		Severe		Poorly suited	
		Slope/erodibility	0.75	Slope/erodibility	0.95	Slope	1.00
		Slope/erodibility	0.50	Slope/erodibility	0.95		
224:							
Zaca	85	Slight		Moderate		Moderately suited	
				Slope/erodibility	0.50	Slope	0.50
						Stickiness; high plasticity index	0.50
						Low strength	0.50
225:							
Zaca	85	Moderate		Severe		Poorly suited	
		Slope/erodibility	0.50	Slope/erodibility	0.95	Slope	1.00
						Stickiness; high plasticity index	0.50
						Low strength	0.50
226:							
Zaca	85	Severe		Severe		Poorly suited	
		Slope/erodibility	0.75	Slope/erodibility	0.95	Slope	1.00
						Stickiness; high plasticity index	0.50
						Low strength	0.50
227:							
Zaca	85	Very severe		Severe		Poorly suited	
		Slope/erodibility	0.95	Slope/erodibility	0.95	Slope	1.00
						Stickiness; high plasticity index	0.50
						Low strength	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Coastal Part

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
228: Water	100	Not rated		Not rated		Not rated	
229: Dams	100	Not rated		Not rated		Not rated	