

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

[The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the potential limitation. The columns that identify the rating class and limiting features show no more than five limitations for any given soil. The soil may have additional limitations. This report shows only the major soils in each map unit]

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
100: Arbuckle	85	Slight		Slight		Well suited	
101: Arbuckle	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
102: Arbuckle	40	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
Positas	30	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
103: Arbuckle	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Positas	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
104: Arbuckle	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Positas	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
105: Arbuckle	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Positas	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
106: Arbuckle	40	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
San Ysidro	20	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
107:							
Arnold	75	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
108:							
Arnold	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
109:							
Ayar	30	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength Stickiness; high plasticity index	0.50 0.50 0.50
Diablo	25	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Low strength Stickiness; high plasticity index	0.50 0.50 0.50
110:							
Ayar	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
Diablo	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
111:							
Ayar	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
111: Diablo	25	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
112: Badland	65	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
113: Balcom	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Calleguas	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
114: Balcom	45	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Nacimiento	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
115: Balcom	45	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Nacimiento	20	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
116: Botella	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
117: Calleguas	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
118: Camarillo	65	Slight		Slight		Poorly suited Flooding	1.00
119: Camarillo	70	Slight		Slight		Moderately suited Low strength	0.50
120: Camatta	80	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50
121: Camatta	80	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
122: Capay	85	Slight		Slight		Moderately suited Stickiness; high plasticity index Low strength	0.50 0.50
123: Capay	75	Slight		Slight		Moderately suited Stickiness; high plasticity index Low strength	0.50 0.50
124: Chanac	85	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
125: Chanac	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
126: Cieneba	75	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
127: Cieneba	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Andregg	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
128: Cieneba	35	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Vista	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
129: Clear Lake	75	Slight		Slight		Moderately suited Flooding Low strength Stickiness; high plasticity index	0.50 0.50 0.50
130: Clear Lake	85	Slight		Slight		Moderately suited Low strength Stickiness; high plasticity index	0.50 0.50
131: Concepcion	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
132: Cropley	75	Slight		Slight		Moderately suited Low strength	0.50
133: Cropley	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
134: Dibble	80	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope Low strength	0.50 0.50
135: Dibble	70	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
136: Dibble	75	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
137: Dibble	85	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
138: Elder	85	Slight		Slight		Moderately suited Low strength	0.50
139: Elder	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
140: Elder	60	Slight		Moderate Slope/erodibility	0.50	Moderately suited Flooding Low strength	0.50 0.50
141: Gaviota	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	20	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
142: Gaviota	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
142: San Andreas	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
143: Gaviota	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
San Andreas	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
144: Gazos	80	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
145: Gazos	80	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
146: Gilroy	50	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	30	Severe Slope/erodibility Slope/erodibility	0.75 0.75	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
147: Hanford	40	Slight		Slight		Well suited	
Greenfield	30	Slight		Slight		Well suited	
148: Hanford	40	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Greenfield	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
149: Hanford	40	Slight		Slight		Well suited	
Greenfield	30	Slight		Slight		Well suited	

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
150:							
Hanford	40	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Greenfield	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
151:							
Henneke	60	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	20	Very severe Slope/erodibility Slope/erodibility	0.95 0.75	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
152:							
Linne	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Calodo	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
153:							
Linne	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Calodo	25	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	1			Not rated		Not rated	
154:							
Linne	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Calodo	25	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
155:							
Linne	40	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Low strength	0.50 0.50
Diablo	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Low strength Stickiness; high plasticity index	0.50 0.50 0.50
156:							
Linne	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Zakme	25	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Stickiness; high plasticity index Low strength	1.00 0.50 0.50
157:							
Lockwood	85	Slight		Slight		Well suited	
158:							
Lockwood	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
159:							
Lockwood	35	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Concepcion	25	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
160:							
Lockwood	40	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Concepcion	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Moderately suited Slope	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
161: Lompico	75	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
162: Lompico	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
McMullin	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
163: Los Osos	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Lodo	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
164: Los Osos	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Rock outcrop	15	Severe Slope/erodibility Slope/erodibility	0.75 0.75	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
165: McMullin	45	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Rock outcrop	20	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
166: Metz	80	Slight		Slight		Well suited	
167: Metz	35	Slight		Slight		Moderately suited Flooding	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
167:							
Tujunga	30	Slight		Slight		Moderately suited Flooding	0.50
168:							
Millsholm	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Ayar	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
169:							
Millsholm	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Dibble	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
170:							
Millsholm	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Dibble	20	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
171:							
Millsholm	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Montara	25	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
172:							
Millsholm	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
172: Rock outcrop	30	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
173: Mocho	75	Slight		Slight		Moderately suited Low strength	0.50
174: Mocho	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
175: Nacimiento	70	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
176: Nacimiento	65	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
177: Nacimiento	35	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Ayar	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50
178: Nacimiento	35	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Ayar	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength Stickiness; high plasticity index	1.00 0.50 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
179:							
Nacimiento	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Los Osos	20	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Slopes of 30 to 50 percent	1			Not rated		Not rated	
180:							
Nacimiento	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Los Osos	20	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
181:							
Nacimiento	35	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Los Osos	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
182:							
Oceano	50	Slight		Moderate Slope/erodibility	0.50	Moderately suited Sandiness Slope	0.50 0.50
183:							
Pico	75	Slight		Slight		Well suited	
184:							
Pico	75	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
185:							
Pits	100	Slight		Slight		Well suited	

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
186: Polonio	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
187: Rincon	80	Slight		Slight		Moderately suited Low strength	0.50
188: Rincon	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
189: Rincon	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope Low strength	0.50 0.50
190: Rock outcrop	60	Very severe Slope/erodibility Slope/erodibility	0.95 0.95	Severe Slope/erodibility Slope/erodibility	0.95 0.95	Poorly suited Slope	1.00
Gaviota	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
191: Ryer	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
192: San Andreas	80	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
193: San Andreas	30	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
Arujo	25	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50
Slopes of 15 to 30 percent	1			Not rated		Not rated	

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
194: San Emigdio	85	Slight		Slight		Well suited	
195: San Emigdio	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
196: San Ysidro	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Slope	0.50
197: San Ysidro	75	Slight		Slight		Moderately suited Low strength	0.50
198: Santa Lucia	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Lopez	25	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
199: Santa Lucia	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Gazos	20	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
200: Sesame	75	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
201: Shimmon	75	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
202: Shimmon	80	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
203:							
Shimmon	40	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Dibble	30	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
204:							
Shimmon	40	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
Dibble	30	Very severe Slope/erodibility	0.95	Severe Slope/erodibility	0.95	Poorly suited Slope Low strength	1.00 0.50
205:							
Sorrento	85	Slight		Slight		Moderately suited Low strength	0.50
206:							
Sorrento	85	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
207:							
Still	85	Slight		Slight		Well suited	
208:							
Still	75	Slight		Slight		Moderately suited Low strength	0.50
209:							
Still	80	Slight		Moderate Slope/erodibility	0.50	Moderately suited Low strength Slope	0.50 0.50
210:							
Vista	75	Slight		Severe Slope/erodibility	0.95	Moderately suited Slope	0.50

Hazard of Erosion and Suitability for Roads on Forestland

San Luis Obispo County, California, Paso Robles Area

Map symbol and soil name	Pct. of map unit	Hazard of off-road or off-trail erosion		Hazard of erosion on roads and trails		Suitability for roads (natural surface)	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
211:							
Vista	40	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
Cieneba	30	Moderate Slope/erodibility	0.50	Severe Slope/erodibility	0.95	Poorly suited Slope	1.00
212:							
Xerofluvents	50	Slight		Slight		Poorly suited Flooding	1.00
Riverwash	30	Slight		Slight		Poorly suited Flooding Wetness Sandiness	1.00 0.50 0.50
213:							
Zakme	85	Severe Slope/erodibility	0.75	Severe Slope/erodibility	0.95	Poorly suited Slope Stickiness; high plasticity index Low strength	1.00 0.50 0.50
214:							
Water	100	Not rated		Not rated		Not rated	